

2021 to 2024

**Q10012408 - ARC-1203-8i will randomly drop
WD8005FRYZ (firmware version: 01.01H101)
disks at create volume.**

This disk command respond over 9 or 10 seconds for create volume some condition. ARC-1203 firmware command timeout default is 8 seconds, so random kick the disks out.

Unique solution ID: #2037

Author: Simone

Last update: 2024-08-15 06:00