

2021 to 2024

**Q10051510 - Z87X-SOC board BIOS F10c
initializes the ARC-1882i consistently when it is
installed.**

The problem was solved by updating the controller firmware to version 1.52
date: 2015-07-21 or later.

Unique solution ID: #1507

Author: Simone

Last update: 2015-10-08 04:46