

2021 to 2024

Q10031702 - CLI 1.14.7 shows for ARC-1883CAP-FBM only "22% loaded" instead of «charged (18.4V)».

This has been fixed, and is included in the CLI, Version: 1.15.1 and ARC-1883 firmware 1.54 date 2017-02-10 or later.

Unique solution ID: #1647

Author: Simone

Last update: 2022-01-06 08:16