

**2021 to 2024**

**Q10011910 - The Seagate Nytro 3031 series +  
1884 controllers mostly all SSDs are detected as  
failed when you do a normal restart.**

It is a hardware compatible issue between the ARC-1884ixl SAS processor and this SSD. The firmware version 1.56-20190911 has added the path to avoid this compatible issue.

Unique solution ID: #1798

Author: Simone

Last update: 2020-08-25 10:46