

2021 to 2024

Q10012103 - After ARC-1203-2I reboot tests with windows version 6.20.0.32, it occurred failed at the 10th restart.

This is the issue for ARC1200 and ARC1203 incorrect doorbell clear which causes OS volume S4 timeout. Update the driver version to Ver. 6.20.0.36 for this workaround.

Unique solution ID: #1953

Author: Simone

Last update: 2021-03-05 03:38