

## **Q10011612 - ARC-1200 can't reboot on the MB which is "HD330-Q87" made by DFI.**

The BIOS on this board default setting is "auto" to detect PCI-e slot speed between Gen 1, Gen 2, Gen 3. Please manual setting M/B BIOS to Gen 1 because ARC-1200 is a Gen 1 card. This unstable situation is happening on speed changing when M/B adjusts PCI-e speed to detect card on each slot.

Unique solution ID: #1633

Author: Simone

Last update: 2022-01-06 08:13