

Q10011702 - ARC-1220 cannot update the firmware 1.39 to 1.49 via DOS utility (nflash).

Older firmware versions support firmware update through web manager console only, so you must execute Archttp proxy software to be able to launch the web manager console for firmware update.

Unique solution ID: #1645

Author: Simone

Last update: 2022-01-06 08:16