

**Q10061705 - ARC-1882ix is enabled the
"Schedule Volume Check" on a time regular base.
But everytime the server did a reboot (update)
the volume check begin.**

It is a time info inquiry bug, and causes abnormal volume check time. This issue is fixed and update firmware version 1.54 date: 2017-03-27 or later to workaround it.

Unique solution ID: #1683

Author: Simone

Last update: 2022-01-06 08:19