

Q10031204 - Using an Areca ARC-1880i with MSI interrupt support on recent versions of DragonFly 3.1 causes disk throughput to slow to a crawl after a while.

Disabling MSI support by setting `hw.arcmsr.msi.enable=0` in `/boot/loader.conf` is enough to make the problem go away.

Unique solution ID: #1348

Author: Simone

Last update: 2022-01-06 08:29