

2021 to 2025

Q10052407 - ARC-1203-8i was working normally as a normal Vmware power on. It has a warm boot problem with a controllerARC-1203-8i and a Supermicro X13sei-tf MB.

Flash Supermicro X13SEI BMC version 1.00.44 to new version is 1.02.04.

This is working on X13SEI.

Unique solution ID: #2024

Author: Simone

Last update: 2024-07-21 15:05