

2018 to 2020

Q10031208 - With the OCZ vertex 4 drives, when Arc-1882ix initialization starts it goes immediately to 100% and then often locks up the raid utility and the initialization never actually starts.

It has fixed by ARC-1882ix firmware version date: 2013-1-3 or later. This firmware also solves the Crucial M4 series SSD compatible issue.

Unique solution ID: #1352

Author: Simone

Last update: 2022-01-06 08:30