

2018 to 2020

Q10031903 - If disk sets to fail in the configuration, the ARC-1214 with the PCB revision 2.0 WebGUI crashes.

Since ARC-1224 uses the new flash chip from the PCB 2.0, please update the firmware to 1.56 2019/02/22 or later version for this workaround.

Unique solution ID: #1779

Author: Simone

Last update: 2020-08-25 10:43