2018 to 2020

Q10051903 - I am having issues installing ARC-1203 driver on CENTOS 3.10.0-957.5.1.el7.x86_64. The kernel driver will no longer load after the update.

A pre-compiled driver module works with the specific kernel version which it built for only. You must compile a new driver module once the kernel is updated. You can refer the readme file in the driver source package for more detail about how to compile the driver and add it into your system.

Unique solution ID: #1781

Author: Simone

Last update: 2020-08-25 10:44