

2015 to 2017

Q10031211 - ARC-1882i pcb version 3.1 (PCIe gen3 enabled) is operating at PCIe2 speeds using ASUS rampage 4 extreme, but it should be at PCIe3. Link status says 8X/5G.

Upgrading M/B BIOS to version 3101 (October 29, 2012), the pcie3 function on the raid card starts to work.

Unique solution ID: #1359

Author: Simone

Last update: 2022-01-06 08:30