

**2014**

## **Q10021407 - ARC-1882ix-24 is resetting all the time and aborts write commands after upgrading Linux kernel from 3.5 to 3.10.**

The kernel building driver is out of date which may not be good enough on these new kernels. Areca has submitted the driver patch to Linux kernel org. Before the driver merges to vanilla kernel tree, the only way to resolve this issue is to make driver by our driver source code.

Unique solution ID: #1139

Author: Simone

Last update: 2015-08-24 09:33