

2014

Q10031303 - ARC-1880ix-16 has a mistake in controller firmware, LED control command did not been properly forwarded. It shows the function "Empty HDD Slot LED" no effect.

This issue had been solved by expander firmware update. Please download the latest expander firmware to solve the empty LED control issue.

ftp://ftp.areca.com.tw/RaidCards/BIOS_Firmware/

Unique solution ID: #1250

Author: Simone

Last update: 2015-08-24 09:56