## 2014

Q10061106 - We have a problem during the installation of the drivers for the ARC-1210 on an ESXi 4.1.0 server. Following your instructions included in the read-me file of the driver package we use the Vmware vSphere CLI. The command "perl -vihostupdate ..." returns the following error message:

## "This operation is NOT supported on 4.1.0 platform."

This problem was caused by the CLI not the latest version. After upgrading to the newest version the driver was successfully installed.

Unique solution ID: #1404

Author: Simone

Last update: 2015-08-25 04:08