

2014

Q10041110 - I am now testing the compatibility issue of the existing driver for ARC-1880LP on "Mac OS X 10.7 Developer Preview Build 4 (Beta version)". I found the existing driver "V.1.33....." will not run on it.

This bug on the kernel driver has been fixed on latest beta revision of Mac OS X 10.7.2 build 11c73. It will come with the official release of Mac OS X 10.7.2 update.

Unique solution ID: #1426

Author: Simone

Last update: 2015-08-25 04:13