

2014

Q10081403 - There is a problem for many repetitive rebooting test of customer's internal test on ARC-1201. Rebooting stop occur in 4 systems of 50 test trial systems.

Reboot test may hang during intensive polling of PCIE link status. It has fixed in bootcode date 2013-01-07 or later.

Unique solution ID: #1081

Author: Simone

Last update: 2015-08-24 09:18