

Q40011602 - ST4000NM0033 Seagate enterprise HDD can't pass self test of ARC-8008 RAID controller shown randomly time out error, when system powers on.

This issue can be fixed by disabling both expander and ROC EDFB function on the ARC-8008 RAID controller or update the firmware to version 1.53

date: 2016-02-16 or later.

Unique solution ID: #1588

Author: Simone

Last update: 2021-02-04 10:27