

Q80022102 - When Mini M1 powers up with ARC-8050T1/T2, ARC-8050 may take a period of time to complete the initialization. If the initialization time is greater than M1 watchdog timeout, it will cause the MAC M1/Pro panic and repeatedly restart.

Please update the firmware to V1.56 2021-01-13 or later version for this workaround.

Unique solution ID: #1945

Author: Simone

Last update: 2022-08-09 03:46