

Q80031704 - On ARC-8050T3-12, we received E#1 FAN #2 Failed errors.

The fan is used for cooling the expander on ARC-8050T3-12. Please update the firmware to version 1.54 date: 2017-04-28 to solve the power on running it at lower speed.

Unique solution ID: #1677

Author: Simone

Last update: 2022-01-06 07:27