

2021 to 2024

Q10041811 - When using X10DRi-F mainboard in UEFI and the ARC-1883LP set to Auto or UEFI mode the system freezes at BIOS 3.0a post code 92 (PCI initialization).

Please update the BIOS code to V1.55 2018-11-01 or later version for this workaround. This workaround also applies X9DRi-LN4F and X9DR3-F

Unique solution ID: #1769

Author: Simone

Last update: 2022-01-06 07:51