

**2012 to 2013**

**Q10011311 - We have an issue on X9SRI-F where  
if we use riser RR1U-E8 it cannot detect the  
ARC-1213-4I RAID controller.**

ARC-1213-4I is not auto detected through the riser by x16 speed especially with E5-2600 v2 processors, the PCI-E link must be forced to x8 to work with LSI 2108 RAID card via riser RR1U-E8. SuperMicro has a workaround BIOS to force PCI-e running at x8 speed.

Unique solution ID: #1293

Author: Simone

Last update: 2015-08-24 11:16