

2016 to 2020

Q30011406 - ARC-1320 Driver - ArcSAS-V2.0.3 can write and read tape using a 1MB buffer on block size set 4M fixed. But if we go to 2MB on the BRU I/O operations, the card fails to allow access to the tape drive at all.

This issue has fixed by ARC-1320 new version driver ArcSAS 2.0.3 Built Jun 25 2012 or later version.

Unique solution ID: #1179

Author: Simone

Last update: 2021-02-04 10:17