

2016 to 2020

Q80011308 - After ARC-8050 firmware updated, ejecting Thunderbolt cable does not turn off power.

We modify the boot sequence in new firmware. This modification may result abnormal start up behavior on 8050 with older firmware codes. A completely Thunderbolt machine power cycle can solve this issue.

Unique solution ID: #1317

Author: Simone

Last update: 2022-01-06 07:10