

2011 to 2015

**Q80011308 - After ARC-8050 firmware updated,
ejecting Thunderbolt cable does not turn off
power.**

We modify the boot sequence in new firmware. This modification may result abnormal start up behavior on 8050 with older firmware codes. A completely Thunderbolt machine power cycle can solve this issue.

Unique solution ID: #1317

Author: Simone

Last update: 2022-01-06 07:10