

2010 to 2015

Q10061412 - Controller fails the brand new hard drive when runs the Hdd Xfer Speed function.

The problem is that the drive is not initialized, so it does not carry overwrite-repair action on factory bad block and cause the read errors. First, you must initialize the drive, and then it will allow you to run Hdd Xfer Speed function.

Unique solution ID: #1219

Author: Simone

Last update: 2022-01-06 07:04