

2010 to 2015

Q60021101- The ARC-5040 performed flawlessly with USB 2.0 and eSATA but when I plug the box into a USB 3.0 port the green light starts blinking and never stops. Even when I unplug the USB 3.0 cable the green light blinks. The computer never sees the connection when using USB 3.0.

If there is no volume for USB port, it will show the behavior as you. You can see the manual for the channel/drive# assign for UBS3.0 volume. Channel/drive# assign for UBS3.0 volume is 0/8~15.

Unique solution ID: #1446

Author: Simone

Last update: 2015-08-24 06:16