

Q10091601 - With ARC-1883LP installed HP Server DL380 gen9, the computer shows an error: Uncorrectable PCI Express Error (Embedded device, Bus 0, Device 0, Function 0, Error status 0x00000000).

This issue can be fixed on ARC-1883 firmware version 1.52 date: 2016-1-28 or later.

Unique solution ID: #1553

Author: Simone

Last update: 2022-01-06 08:09