

Q10041603 - ARC-1882ix/4GB with battery is suddenly powered off. It is shown F/W detects: **SDRAM speed not enough!! on screen before get into OS.**

It is the compatibility of RAID controller with some DIMM modules. This issue can be solved with the firmware bootcode version 1.53 date: 2016-03-28 or later.

Unique solution ID: #1592

Author: Simone

Last update: 2022-01-06 08:10