

**2016**

## **Q10021405 - ARC-1882 can not detect the ST4000VN000.**

Seagate ST4000VN000 6G SATA drive SC44 firmware manufacture current allowance speed default set on 1.5Gb/s even its capability=6Gb/s. The PL firmware phase 17 or later can not work with 1.5Gb/s SATA speed. This issue can be solved by manually configuring drives to SATA 6G mode by 'Seagate SATA HDD Speed=6G' function on the Advanced Configuration.

Unique solution ID: #1124

Author: Simone

Last update: 2015-08-24 09:29