

**2015**

**Q10021505 - ST4000NM0033 Seagate enterprise HDD can't pass self test of ARC-1883ix-16 shown randomly fail, when system powers on.**

This issue can be fixed by disabling both expander and ROC EDFB function on the ARC-1880ix-16.

Unique solution ID: #1153

Author: Simone

Last update: 2016-02-01 09:41