

**2013**

**Q10031303 - ARC-1880ix-16 has a mistake in controller firmware, LED control command did not been properly forwarded. It shows the function "Empty HDD Slot LED" no effect.**

This issue had been solved by expander firmware update. Please download the latest expander firmware to solve the empty LED control issue.

[ftp://ftp.areca.com.tw/RaidCards/BIOS\\_Firmware/](ftp://ftp.areca.com.tw/RaidCards/BIOS_Firmware/)

Unique solution ID: #1250

Author: Simone

Last update: 2015-08-24 09:56