

2021 to 2023

**Q80042209 - When the multiple
ARC-8050T3U-12E are connected in series on the
M1 mac studio system, sometimes it does not
recognize the secondary one, and only first one
can be seen in the management interface.**

Update the firmware to V1.64 2022-09-15 or later version for this workaround.

Unique solution ID: #2013

Author: Simone

Last update: 2022-09-17 14:21