

**2017**

**Q80021708 - Since updating to macOS Sierra,  
ARC-8050T2 cannot boot from the Apple  
Thunderbolt 3 machine using Thunderbolt 3 (USB-  
C) to Thunderbolt 2 Adapter.**

Apple macOS 10.12.3 and 10.12.4 have issue to load the devices Option ROM firmware by pressing "Option-Shift-Command-Period" at the [Startup Manager](#) window. As a result, your Mac doesn't see ARC-8050T2 that has Option ROM firmware. This issue has been fixed on the macOS 10.12.5 or later version.

Unique solution ID: #1709

Author: Simone

Last update: 2017-08-22 09:26