

2010 to 2015

**Q60011311 - How do I enable ARC-5040 USB 3.0?
USB 2.0 works but when plugged in via USB 3.0
the access light only flashes. No device is made
available to the OS.**

USB 2.0 and 3.0 use different configurations, please make sure you properly configure volumes and controller setting.

USB 2.0 port mapping to volumes with channel 1, driv 0-7

USB 3.0 port mapping to volumes with channel 0, driv 8-15, and the 'USB3.0/1394 Select' setting must configure change to USB 3.0.

Unique solution ID: #1313

Author: Simone

Last update: 2021-02-04 10:49