Q10061412 - Controller fails the brand new hard drive when runs the Hdd Xfer Speed function.

The problem is that the drive is not initialized, so it does not carry overwrite-repair a ction on factory bad bock and cause the read errors. First, you must initialize the dri ve, and then it will allow you to run Hdd Xfer Speed function.

Unique solution ID: #1219
Author: Simone
Last update: 2022-01-06 07:04

(c) 2025 Vincent C. <vincent_chen@abacid.com> | 2025-07-04 12:52
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=0&id=220&artlang=en