2018 to 2020

Q10011703 - Every time hot swap WD gold drive (WD4002FYYZ) drive on ARC-1203-8i, all other drives will be kicked out.

This issue has fixed, and is included in the ARC-1203 firmware version 1.54 data: 2017-02-14 or later.

Unique solution ID: #1653

Author: Simone

Last update: 2022-01-06 08:17

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-29 09:56

URL: http://faq.areca.com.tw//index.php?action=artikel&cat=10&id=654&artlang=en