Q30011503 - Ubuntu kernel version 3.5.17 gets kernel panic after ARC-1320 HBA driver is loaded with a Quantum Ultrium 6 drive (Model: AQ285A#900) using LTFS.

These known LTFS issues were fixed by the driver version 1.1.6.141103.

Unique solution ID: #1041
Author: Simone
Last update: 2015-08-24 09:48

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-28 21:54
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=0&id=42&artlang=en