2016 to 2020

Q80011503 - ARC-5026 unit is spontaneously powering off -- and immediately powering on.

The problem turned out to be a defective Corning electro-optical Thunderbolt cable that was causing the ARC-5026 to power-cycle every few seconds.

Unique solution ID: #1066
Author: Simone
Last update: 2022-01-06 07:16

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-19 08:15
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=36&id=67&artlang=en