2021 to 2023

Q10061705 - ARC-1882ix is enabled the "Schedule Volume Check" on a time regular base. But everytime the server did a reboot (update) the volume check begin.

It is a time info inquiry bug, and causes abnormal volume check time. This issue is fixed and update firmware version 1.54 date: 2017-03-27 or later to workaround it.

Unique solution ID: #1683
Author: Simone
Last update: 2022-01-06 08:19

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-29 01:56
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=8&id=684&artlang=en