2018 to 2020

Q10042003 - The Supermicro X11SCH-LN4F can not find the ARC-1203 after initialization.

The default setting of PEG Max link speed is Auto. The system will initial pcie to train the pcie link speed and capability during cold boot. After a warm reset, pcie reset time might cause pcie re-train unstable and system cannot recognize the card. Due to the Raid ARC-1203 card is PCIE 2.0 Gen2, we suggest that forcing pcie speed down to Gen2.

Unique solution ID: #1897
Author: Simone
Last update: 2022-01-06 07:37