2024

Q90042408 - Intel MAC via Thunderbolt 3 to ARC-1686 or 1886, the revision / firmware # of the device shows as "R001" regardless of what the device is.

Areca RAID controller does not present physical drives to the operating system, only logical drives. The logical drivers (volumes) revision / firmware # from the controller firmware will always assign as "R001" regardless of what the device is connected. For Tape device, please update to version 1.70 or later to get correct firmware version from tape device.

Unique solution ID: #2041
Author: Simone
Last update: 2024-08-15 06:20