Q10061510 - Samsung SSD 850 PRO 1TB Firmware Version = EXM02B6Q drives are showing "Time Out Error".

Disable SATA NCQ support in controller setting fixes this compatibile issue.

Unique solution ID: #1508
Author: Simone
Last update: 2015-10-13 11:20

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-19 02:21
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=0&id=509&artlang=en