# 2011 to 2015

# Q80011403 - ARC-8050T2 can not work on MacBook Air with OSX 10.7.5, but New Mac Pro is ok.

Thunderbolt 2 can only work on Mac OS X 10.8.5 or higher.

Unique solution ID: #1226

Author: Simone

Last update: 2015-08-24 08:27



**(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-28 17:47**

URL: http://faq.areca.com.tw//index.php?action=artikel&cat=60&id=227&artlang=en