Q10021703 - ARC-1883ix cannot see any HDD when HGST JBOD 4U60 is set as SES mode.

This issue has been fixed in ARC-1883ix expander firmware version 03.01.27.51 06/06/16 or later.

Unique solution ID: #1654
Author: Simone
Last update: 2022-01-06 08:17

(c) 2024 Vincent C. <vincent_chen@abacid.com> | 2024-03-19 11:49
URL: http://faq.areca.com.tw//index.php?action=artikel&cat=0&id=655&artlang=en