

**2021 to 2024**

**Q10031706 - When the Intel SP1200SPS M/B boots up the ARC-1201 card, the RAID adapter BIOS spits out this error "F/W Detected Unknown Error".**

This issue can be fixed by updating firmware and boot code to the 1.51 version.

p;User disabled rom on that port there no longer have issues.

Unique solution ID: #1692

Author: Simone

Last update: 2022-01-06 08:20