

2021 to 2024

**Q10012111 - M.2 NVMe MICRON 7300PRO x1 on
ARC-1886-6N2I creates RAID0 and found that M.2
MICRON 7300Pro is fail.**

Due to this NVME did't support Common Clock mode, therefore it should be forced to SRIS mode on the RAID card. Please modify the corresponding clock configuration to SRIS mode. The corresponding clock configuration setting is available in Advanced Feature menu.

Unique solution ID: #1974

Author: Simone

Last update: 2021-11-23 09:24