

Q10091405 - When upgrading the firmware of the ARC-1882X, I get the error “HTTP protocol error 3” with ArchHTTP version 2.4.0 under Windows 7 (Internet Explorer 11).

This issue may occur if we use 6.20.00.21 driver. There is no issue using ArchHTTP version 2.4.0 with driver 6.20.00.29 under Windows 7 and IE11.

Unique solution ID: #1131

Author: Simone

Last update: 2015-08-24 09:31